Oil Field Environmental Incident Summary

Responsible Party: ENDURO OPERATING, LLC **Well Operator:** ENDURO OPERATING, LLC

Well Name: BULL MOOSE 22Y-32

Field Name: BULL MOOSE Well File #: 19765

Date Incident:10/19/2015Time Incident:08.00Facility ID Number:County:MCKENZIETwp:147Rng:101Sec:22Qtr:

Location Description:

Submitted By: Rodney Conway Received By:

Contact Person: Rodney Conway

777 MAIN STREET

SUITE 800

FORT WORTH, TX 76102

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: Unknown
Spilled Units Recovered Units Followup Units
Oil 4 Barrels 4 Barrels 4 barrels

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 10/29/2015 Clean Up Concluded: 10/20/2015

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

Well shut in. all safety equipment checked and all works. Clean up started and will finish today

Wastes Disposal Location: IHD

Agencies Involved:

Updates

Date: 10/20/2015 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. NDIC retains oversight.